




## Why BKM PRIME AE JV Team



## Core Data

- + **UEI:** NDLQWZF6Z1E8
- + **Cage Code:** 9CFY8
- + **NAICS Code:** 541330
- + **Classification:** Small Business

## Full Service JV

3D Scanning  
Architecture  
AV/IT  
Bridge Design & Inspection  
Building Envelope  
Civil Engineering  
Construction Mgmt. / Inspection  
Electrical Engineering  
Energy Modeling  
Fire Protection  
GIS  
Interior Design  
Landscape Architecture  
Lighting Design  
Master Planning  
Mechanical Engineering  
Plumbing Engineering  
Programming  
Structural Engineering  
Surveying  
Traffic Engineering  
Transportation Engineering  
Water/Wastewater Engineering  
Water Resources

## Points of Contact



**ANTHONY PAGE,**  
**PE, LEED AP**  
JV Managing Partner  
P: (443) 956-9884  
apage@bkma.com  
www.bkma.com




**ED CHAMBERLAYNE,**  
**PHD, PE, F.SAME**  
Deputy JV Managing Partner  
P: (410) 862-0911  
ed.chamberlayne@primeeng.com  
www.primeeng.com

Electronic Version:  
BKM | PRIME AE JV  
Capabilities



## Air Force Installations where BKM PRIME JV has Designed Projects



### Air Reserve Station Minneapolis

- Bldg. 750 Renovation and Addition
- Civil Engineering Storage Facility

### Arnold Air Force Base

- Sewage Treatment Plant Bldg 1552
- Cathodic Protection Repair
- Warehouse Charrette and Design

### Cannon Air Force Base

- Design of Water Infrastructure, Melrose Air Force Range
- Repair of Chindit Boulevard from Main Gate to H119

### Dobbins Air Reserve Base

- Building #729 & #744, Roof Repairs - HQ Facility
- RFP Development Entry Control

### Dover Air Force Base

- Overhead Electrical to Underground

### Dyess Air Force Base

- Renovation of Building 7232
- Repair Hangar Building 5110
- Repair of Chapel Building 6620
- Repair of Doors, AGE Maintenance Shop B9198
- Renovate B8031 Secure Facility Title II Services

### Eglin Air Force Base

- McKinley Climatic Laboratory Bldg
- F-35 Add/Alter Squadron Ops B64
- Charette for the 36th EWS Reprogramming Center
- C-74 Kinetic Energy Munitions Test Facility Charrette
- Develop D/B RFP for F-35A Consolidated HQ Facility
- Charrette for Fabrication and Analysis Center
- Working Dog Treatment Facility Replacement DB RFP

### Joint Base Langley-Eustis

- Bldg 698 Dorm Planning Charrette

### Grissom Air Reserve Base

- Roof Replacement Nose Dock Hangar 6 Roof, Building 434
- Master Plan and Design for Renovation of Building 667

### Joint Base Andrews

- Development DB RFPs for Reno of Bldgs 1560, 1914, 1915
- Repair Hangars 6 and 7
- Alter ATFP Virginia Avenue Gate
- Repair Roof 89AW PAG Hangar Bldg 5016
- Upgrades for Substation Bldg 1870

### Joint Base Maguire-Dix-Lakehurst

- Replace Fire Pumps at Hangar 1837
- Design Replacement of Well No. 6

### Joint Base San Antonio Lackland

- Repair Dorm B861 HVAC / Electrical
- Repair and Renovate Student Dorm Bldg 10656
- Structural Analysis and Repair of Building B2007 (SCIF)
- Bridge Inspection and Survey

### Kirtland Air Force Base

- Substation 3 Demo and Substation 10 Reconstruction
- Replace HVAC Hangar 1001
- Repair Taxiway to Hot Cargo Pad 5 Title II Services
- Repair Dorm B20351 HVAC System
- Fire Protection Upgrades Bldg 27496

### Little Rock Air Force Base

- Repair All American Landing Zone

### MacDill Air Force Base

- Renovation of SSOCOM Building 102
- KC-46A Supplies and Equipment Warehouse
- Renovation of SOCOM Building 102
- HQ CENTCOM CUP Reliability Assessment

### Malmstrom Air Force Base

- Bldg 152 Booster Pump #3 Eval
- Repair HVAC Bldg 780

### Minot Air Force Base

- Renovation of Dormitories 130 & 131
- Develop D-B RFP for Reno of Communication Building 121

### Offutt Air Force Base

- Conceptual Charrette Report for Repair of B40

### Robins Air Force Base

- Renovation of Bldg 1602
- Develop DB RFPs for Reno/Add to Six AFRC Facilities
- Add/Alt to Aircraft Corrosion Control Facility, Bldg 180
- Develop DB RFP Addition to Bldg 651
- Develop DB RFP for New Administration Building Near B903
- Replace Generator Facility 226C, Bldg 229

### Tinker Air Force Base

- Repair Midkiff Hall Dormitory B5903
- Repair Dormitory B5913

### Tyndall Air Force Base

- Damage and Repair Assessments, Hurricane Michael
- DB RFP for Air Battle Management Simulator Facility
- DB RFP Temporary Hangar & Sabre Gate

### US Air Force Academy

- Independent Cost Estimating for Repair of Cadet Chapel

### Wright-Patterson Air Force Base

- Planning Charrette Report for Repair/Renovation AFMC HQ
- Repair Primary Runway 05/23L and Taxiways A, D, and C
- Title II Services For Convert F/20006 For Program Executive Office (PEO)